



H13-341^{Q&As}

Huawei Certified internetwork Expert - Transmission

Pass Huawei H13-341 Exam with 100% Guarantee

Free Download Real Questions & Answers **PDF** and **VCE** file from:

<https://www.passapply.com/h13-341.html>

100% Passing Guarantee
100% Money Back Assurance

Following Questions and Answers are all new published by Huawei
Official Exam Center

-  **Instant Download** After Purchase
-  **100% Money Back** Guarantee
-  **365 Days** Free Update
-  **800,000+** Satisfied Customers





QUESTION 1

If OCh trails fail to be created by trail, which are possible causes?

- A. There are still alarms that are not cleared on the boards involved in the OCh.
- B. The wavelength settings at the source and sink ends are inconsistent.
- C. Some fibers are not connected.
- D. There is no server trail.

Correct Answer: D

QUESTION 2

Which of the following statements about the Service Package is incorrect?

- A. You can configure service package in two modes. One is to configure boards in batches, and the other is to configure each board.
- B. Service package enables one-click configuration of typical services by issuing multiple configuration commands in batches, facilitating product deployment commissioning and reducing maintenance costs.
- C. The Service Package can configure the working mode, service type, cross-connection, and port type in batches.
- D. Currently, Service Package is available to the TOA, TOX and TSC boards.

Correct Answer: D

QUESTION 3

Which of the following alarms trigger optical line protection switching?

- A. POWER_DIFF_OVER
- B. R_LOF
- C. MUT_LOS
- D. R_LOS

Correct Answer: A

QUESTION 4

FXS and FXO are the names of the ports used by analog telephone lines. FXO ports and FXS ports are always used in pairs.



- A. True
- B. False

Correct Answer: B

QUESTION 5

Which of the following statements about AU pointers are correct?

- A. The root cause of the AU pointer justification is that the clocks of the upstream and downstream stations are not synchronized.
- B. AU_PTR indicates the position of the J0 byte.
- C. If the receive end detects that the H1H2 bytes are "1", the local end generates the AU-AIS alarm.
- D. The value of the AU-PTR pointer is placed in the last 10 bits of the H1 and H2 bytes. Therefore, the valid value of the AU-PTR pointer is 0~1023.

Correct Answer: C

[Latest H13-341 Dumps](#)

[H13-341 PDF Dumps](#)

[H13-341 Exam Questions](#)