DES-4421^Q&As

Specialist - Implementation Engineer, PowerEdge MX Modular Exam

Pass EMC DES-4421 Exam with 100% Guarantee

Free Download Real Questions & Answers **PDF** and **VCE** file from:

https://www.passapply.com/des-4421.html

100% Passing Guarantee
100% Money Back Assurance

Following Questions and Answers are all new published by EMC Official Exam Center

QUESTION 1

What is the maximum possible weight of a fully populated MX7000 chassis?

A. 250 lbs (114 kg)

B. 300 lbs (136 kg)

C. 400 lbs (182 kg)

D. 500 lbs (227 kg)

Correct Answer: C

Reference: https://www.dell.com/support/manuals/us/en/04/poweredge-mx7000/pemx7000_ts_pub/chassis-weight?guid=guid-41294709-f48d-4174-846d-2fefc1483aefandlang=en-us

QUESTION 2

Which controller option the mapping of an entire MX5016s to multiple compute sleds?

A. PERC H730 only

B. HBA330 only

C. H745 Jumbo PERC

D. HBA330 and PERC H730

Correct Answer: B

Reference: https://www.dell.com/support/manuals/us/en/04/poweredge-mx7000/pemx5016s_mx5000s_ism/initial-system-setup-and-configuration-for-mx5016s?guid=guid-f5a47d05-b0f9-4573-aa98-350a7e7a2c3candlang=en-us

QUESTION 3

What can be used as the firmware update source for OME-M within an MX chassis?

A. Server Update Utility Baseline from a Catalog

B. Server Update Utility System Live Image (SLI)

C. Dell Update package System Live Image (SLI)

D. Dell Update Package Baseline from a Catalog

Correct Answer: D

Reference: https://topics-cdn.dell.com/pdf/openmanage-enterprise-modular-v10001-poweredge-mx7000_users-guide4_en-us.pdf

QUESTION 4

An administrator is configuring a fully populated MX5016s storage sled to be accessed by four MX740c compute sleds. Each compute sled has an H745P Jumbo PERC installed. The disks in the storage sled are evenly distributed across all compute sleds using a Drive-Assigned storage configuration.

What is the maximum number of disks that each compute sled can detect from the MX5016s?

A. 1

B. 2

C. 4

D. 16

Correct Answer: D

Reference: https://www.dell.com/en-us/work/shop/povw/poweredge-mx5016s

QUESTION 5

A technician has replaced an MX chassis tub. They complete the tub installation and power on the chassis. They notice that the KVM is no longer functional. What should the technician do after confirming the KVM feature is still enabled in OME-M?

A. Ensure all cables connecting the tub to the left ear control panel are connected properly

B. Ensure all power supplies are connected and powered-on

C. Ensure all cables connecting the tub to the right ear control panel are connected properly

D. Ensure all installed Management Modules are connected to the network

Correct Answer: A