



# DES-4421<sup>Q&As</sup>

Specialist - Implementation Engineer, PowerEdge MX Modular Exam

**Pass EMC DES-4421 Exam with 100% Guarantee**

Free Download Real Questions & Answers **PDF** and **VCE** file from:

<https://www.passapply.com/des-4421.html>

100% Passing Guarantee  
100% Money Back Assurance

Following Questions and Answers are all new published by EMC  
Official Exam Center

-  **Instant Download** After Purchase
-  **100% Money Back** Guarantee
-  **365 Days** Free Update
-  **800,000+** Satisfied Customers





### QUESTION 1

While servicing an MX7000 chassis a system administrator logs into OME-M and receives a Chassis Mismatch error. What should be the next step taken by the administrator?

- A. Clear the configuration
- B. Reset Peer or the Local IOM
- C. Perform firmware update
- D. Force Active/Clear configuration

Correct Answer: D

Reference: [https://topics-cdn.dell.com/pdf/openmanage-enterprise-modular-v10001-poweredge-mx7000\\_users-guide4\\_en-us.pdf](https://topics-cdn.dell.com/pdf/openmanage-enterprise-modular-v10001-poweredge-mx7000_users-guide4_en-us.pdf)

---

### QUESTION 2

Which protocol(s) does Redfish use?

- A. JSON and OData only
- B. JSON only
- C. JSON, OData, and SNMP
- D. OData only

Correct Answer: A

Reference: <https://www.dell.com/support/article/us/en/04/sln310624/redfish?lang=en>

---

### QUESTION 3

An MX7000 administrator has been tasked to perform the initial configuration of a new MX platform. The MX700 has seven MX740c, one MX5016s, two Management Modules (MMs), an LED-Only control panel, two MX9116n in Fabric A, two MX5108n in Fabric B, and two MX5000s in Fabric C.

What is a valid method to perform the initial MX platform configuration?

- A. Use a serial DB9 / DB cable
- B. Use KVM and racadm setniccfg command from MM configuration menu
- C. Use Ethernet front panel port default DHCP address
- D. Use QuickSync 2

Correct Answer: D



Reference:

<https://infohub.delltechnologies.com/static/media/client/7phukh/d3df87a5-ddb7-4917-969d-24e249b52824.pdf>

---

#### QUESTION 4

An administrator has installed the iDRAC Service Module in the OS on a compute sled, they are unable to use its features in the iDRAC web GUI. What is the likely cause of this issue?

- A. OS to iDRAC pass-through feature is not enabled in the iDRAC
- B. iDRAC Express license is installed
- C. OS and iDRAC are configured on different networks
- D. Installed OS is not supported

Correct Answer: A

Reference: <https://cdn.cnetcontent.com/syndication/mediaserver/inlinecontent/all/0ec/190/0ec19016bfa8284323b12b2aa8d7a07c/original.pdf>

---

#### QUESTION 5

Which I/O module(s) supports Full Switch and SmartFabric operating modes?

- A. MX9116n and MX5108n
- B. MX5108 and MX5016s
- C. MX9116n only
- D. MX9116 and MX7116n

Correct Answer: A

Reference: <https://infohub.delltechnologies.com/l/poweredge-mx-smartfabric-configuration-and-troubleshooting-guide-12/operating-modes-35>

[Latest DES-4421 Dumps](#)

[DES-4421 Study Guide](#)

[DES-4421 Brindumps](#)